

Full credit is given to the above companies including the OS that this PDF file was generated!

Rocky Enterprise Linux 9.2 Manual Pages on command 'nvme-sanitize.1'

\$ man nvme-sanitize.1

NVME-SANITIZE(1)

NVMe Manual

NVME-SANITIZE(1)

NAME

nvme-sanitize - Send NVMe Sanitize Command, return result

SYNOPSIS

nvme sanitize <device> [--no-dealloc | -d]

[--oipbp | -i]

[--owpass=<overwrite-pass-count> | -n <overwrite-pass-count>]

[--ause | -u]

[--sanact=<action> | -a <action>]

[--ovrpat=<overwrite-pattern> | -p <overwrite-pattern>]

[--force]

DESCRIPTION

For the NVMe device given, sends a Sanitize command and provides the

result.

The <device> parameter is mandatory NVMe character device (ex:

/dev/nvme0).

On success it returns 0, error code otherwise.

-d, --no-dealloc

No Deallocate After Sanitize: If set, then the controller shall not deallocate any logical blocks as a result of successfully completing the sanitize operation. If cleared, then the controller should deallocate logical blocks as a result of successfully completing the sanitize operation. This bit shall be ignored if the Sanitize Action field is set to 001b (i.e., Exit Failure Mode).

-i, --oipbp

Overwrite Invert Pattern Between Passes: If set, then the Overwrite Pattern shall be inverted between passes. If cleared, then the overwrite pattern shall not be inverted between passes. This bit shall be ignored unless the Sanitize Action field is set to 011b (i.e., Overwrite).

-n <overwrite-pass-count>, --owpass=<overwrite-pass-count> Overwrite Pass Count: This field specifies the number of overwrite passes (i.e., how many times the media is to be overwritten) using the data from the Overwrite Pattern field of this command. A value of 0 specifies 16 overwrite passes. This field shall be ignored unless the Sanitize Action field is set to 011b (i.e., Overwrite).

-u, --ause

Allow Unrestricted Sanitize Exit: If set, then the sanitize operation is performed in unrestricted completion mode. If cleared then the sanitize operation is performed in restricted completion mode. This bit shall be ignored if the Sanitize Action field is set to 001b (i.e., Exit Failure Mode).

-a <action>, --sanact=<action>

Sanitize Action:

?

?Value ? Definition

?0x00 ? Reserved ?

?0x01 ? Exit Failure Mode ?

?0x02 ? Start a Block Erase ?

? ? sanitize operation ?

?0x03 ? Start an Overwrite ?

? ? sanitize operation ?

?0x04 ? Start a Crypto Erase ?

? ? sanitize operation ?

-p <overwrite-pattern>, --ovrpat=<overwrite-pattern>

Overwrite Pattern: This field is ignored unless the Sanitize Action

field in Command Dword 10 is set to 011b (i.e., Overwrite). This

field specifies a 32-bit pattern that is used for the Overwrite

sanitize operation.

--force

Ignore namespace is currently busy and performed the operation even

though.

EXAMPLES

? Has the program issue Sanitize Command :

nvme sanitize /dev/nvme0n1 -a 0x02

nvme sanitize /dev/nvme0n1 --sanact=0x01

NVME

Part of the nvme-user suite.

NVMe 06/23/2023 NVME-SANITIZE(1)